HINGHAM PUBLIC SCHOOLS 2021-2022 Capital Projects

select

Row Labels	Sum of FY 2021	Sum of FY 2022	Sum of FY 2023	Sum of FY 2024	Sum of FY 2025	Sum of FY 2026
Article	\$0	\$4,190,190	\$0	\$0	\$0	\$0
Majority Vote Approval for entering into a bus lease to extend						
over a five year period.	\$0	\$1	\$0	\$0	\$0	\$0
Windows / Doors - Replace windows per the 10 year master plan	\$0	\$4,190,189	\$0	\$0	\$0	\$0
East	\$66,500	\$45,000	\$85,000	\$50,000	\$50,000	\$50,000
Building Repairs and Improvements	\$0	\$0	\$50,000	\$50,000	\$50,000	\$50,000
Flag Pole Lighting	\$0	\$0	\$5,000	\$0	\$0	\$0
Improve PA system sound - exterior	\$0	\$0	\$0	\$0	\$0	\$0
Inspection Waster Water Pumps	\$8,000	\$0	\$0	\$0	\$0	\$0
LED Lighting Upgrade	\$0	\$0	\$20,000	\$0	\$0	\$0
Stage Refinished	\$0	\$0	\$10,000	\$0	\$0	\$0
HVAC Duct Maintenance & Test	\$20,000	\$0	\$0	\$0	\$0	\$0
Energy Recovery Units (ERU's) damper replacement	\$38,500	\$0	\$0	\$0	\$0	\$0
Playground Equipment	\$0	\$5,000	\$0	\$0	\$0	\$0
Replace Chiller Coils	\$0	\$40,000	\$0	\$0	\$0	\$0
Foster	\$0	\$0	\$0	\$0	\$233,000	\$0
Flag Pole Lighting	\$0	\$0	\$0	\$0	\$5,000	\$0
FOB Station for Presentation Room Door	\$0	\$0	\$0	\$0	\$0	\$0
Playground - ADA Playground Compliance	\$0	\$0	\$0	\$0	\$84,000	\$0
Playground Edging	\$0	\$0	\$0	\$0	\$20,000	\$0
Building Envelope Repairs	\$0	\$0	\$0	\$0	\$30,000	\$0
Exterior Lighting	\$0	\$0	\$0	\$0	\$10,000	\$0
Playground - ADA Compliance	\$0	\$0	\$0	\$0	\$84,000	\$0

Status

		2021-2022 Cap				
Row Labels	Sum of FY 2021		•	Sum of FY 2024	Sum of FY 2025	Sum of FY 2026
HHS	\$286,150				\$421,460	\$165,000
Boiler- Heat - Removal of Underground Oil Tank	\$0			•	\$0	\$0
Boiler replacement - Heat - Bidding and Construction	\$C				\$0	\$0
Boiler Replacement - Heat -Feasibility Study	\$C) \$C			\$0	\$0
Build Wall in Guidance between learning spaces	\$0) \$C	\$0	\$0	\$0	\$0
Building Repairs and Improvements	\$C) \$C	\$75,000	\$75,000	\$75,000	\$75,000
Counter Tops In Art Lab	\$C) \$C			\$0	\$0
Fields and Grounds - Resurface the Track	\$C) \$C	\$100,000	\$0	\$0	\$0
Fire Alarm Upgrade	\$C) \$C	\$0	\$0	\$0	\$0
Floors - Refinish all boys and girls' locker room floors	\$C) \$C	\$0	\$75,859	\$0	\$0
Resolve Sewar Issue Outside Guidance Office	\$C) \$C	\$0	\$0	\$80,000	\$0
Roof - For existing concession building	\$C) \$C	\$0	\$0	\$20,000	\$0
Safety - Sprinkler Head Replacement	\$33,000) \$C	\$0	\$0	\$0	\$0
Speaker Announcement PA and Clock System	\$C) \$C	\$0	\$0	\$0	\$0
Unanticipated Major Repairs	\$25,000	\$25,000	\$0	\$0	\$0	\$0
Court Yard Improvements	\$C			\$0	\$8,960	\$0
Painting Hall Way Ceilings	\$C) \$C	\$12,924	\$0	\$0	\$C
Replace Wrestling Room Floor	\$C	\$36,535			\$0	\$0
Gym Bleacher Maintenance	\$20,150) \$C	\$0	\$0	\$0	\$C
Concrete work on exterior of building	\$C	\$25,000	\$0	\$0	\$0	\$0
General HVAC Mechanical and/or Electrical Upgrades	\$25,000) \$C	\$0	\$0	\$0	\$0
HVAC Duct Maintenance & Test	\$20,000) \$C	\$0	\$0	\$20,000	\$0
Mechanical System Piping Replacement	\$50,000) \$C	\$0	\$0	\$0	\$0
Replace VCT flooring	\$C) \$C	\$0	\$0	\$10,000	\$0
Building Envelope Repairs	\$C) \$C	\$0	\$0	\$75,000	\$0
Exterior electrical fixtures for concession stand	\$C) \$C	\$5,825	\$0	\$0	\$0
(2) Heating Boiler Exausto System	\$C	\$12,000	\$0	\$0	\$0	\$0
Playground at the preschool site for Child Development	\$C		\$0	\$0	\$7,500	\$0
Woodshop slop sink	\$C) \$C	\$0	\$0	\$10,000	\$0
Replace IT Server Room AC Unit	\$13,000) \$C	\$0	\$0	\$0	\$0
Design Atrium	\$C) \$C	\$0	\$0	\$25,000	\$0
Gym Glass Windows -Complete FY 20	\$C) \$C	\$0	\$0	\$0	\$0
Enegy Efficiency - Interior Lighting upgrade with LED Ongoing pr	rc \$C) \$C	\$20,000	\$20,000	\$20,000	\$20,000
Fields - Resurface Tennis Courts	\$C) \$C	\$0	\$80,000	\$0	\$0
Heat - Rooftop Air Handler Replacement	\$C	\$60,000	\$60,000	\$0	\$0	\$0
PM- Rebuild Mechnaical Pumps, Regular and Chill Water	\$C) \$C	\$0	\$0	\$0	\$0
PM - Ventilation Fans for Crawl Space tunnel	\$C	\$10,000	\$0	\$0	\$0	\$0
Field - Turf Replacement	\$C) \$C	\$578,813	\$0	\$0	\$0
Energy - Energy Management System - Upgrade parts to ONA .	\$20,000	\$20,000	\$20,000	\$20,000	\$20,000	\$20,000
Replace BACnet IP based communication system devices and co					\$50,000	\$50,000
Windows and Doors	\$30,000				\$0	\$0

Row Labels Sum of FY 2021 Sum of FY 2022 Sum of FY 2023 Sum of FY 2024 Sum of FY 2025 Sum of FY 2			2021-2022 Capi				
MS 540,000 \$20,000 \$35,000 \$154,500 \$20,000 Asphalt Freiane side of Building \$0 \$0 \$0 \$20,000 <t< th=""><th>₹ow Labels</th><th>Sum of FY 2021</th><th>•</th><th>•</th><th>Sum of FY 2024</th><th>Sum of FY 2025</th><th>Sum of FY 2026</th></t<>	₹ow Labels	Sum of FY 2021	•	•	Sum of FY 2024	Sum of FY 2025	Sum of FY 2026
Asphalt Firelane side of Building \$0 \$0 \$0 \$0 \$0 \$50 \$50 \$50 Building Repairs and Improvements \$20,000							
Field rainage \$0 \$0 \$10 \$12,0,000 Slop Sinks in Tech Lab and Woodworking Lab \$0 <td>Asphalt Firelane side of Building</td> <td>•</td> <td>•</td> <td>•</td> <td>•</td> <td></td> <td>· · ·</td>	Asphalt Firelane side of Building	•	•	•	•		· · ·
Field rainage \$0 \$0 \$10 \$12,0,000 Slop Sinks in Tech Lab and Woodworking Lab \$0 <td>Building Repairs and Improvements</td> <td>\$20,000</td> <td></td> <td></td> <td></td> <td></td> <td></td>	Building Repairs and Improvements	\$20,000					
Line stone in acid nuetralization tank \$0 \$0 \$10 \$10 \$0 Grounds Improvements \$20,000 \$60 \$0 \$0 \$0 \$0 PRS \$80,000 \$457,348 \$106,000 \$59,800 \$50,000	Field drainage			\$0			
Grounds Improvements \$20,000 \$0 \$0 \$0 Asphalt - Waster Water Treatment Plant entry \$0 \$60,000 \$0 \$0 \$0 \$0 Building Repairs and Improvements \$00,000 \$457,348 \$106,000 \$50,000 <	Slop Sinks in Tech Lab and Woodworking Lab	\$0	\$0	\$0	\$0	\$8,000	\$0
Grounds Improvements \$20,000 \$0 \$0 \$0 Asphalt - Waster Water Treatment Plant entry \$0 \$60,000 \$60,000 \$60,800 \$149,400 \$50,000 Building Repairs and Improvements \$0 \$100,000 \$0 \$50,000	Lime stone in acid nuetralization tank	\$0	\$0	\$0	\$15,000	\$0	\$0
PRS \$80,000 \$457,348 \$106,000 \$69,800 \$149,400 \$50, Building Repairs and Improvements \$0 \$10,000 \$0 \$50,000	Grounds Improvements	\$20,000	\$0	\$0			\$0
Building Repairs and Improvements \$0 \$0 \$0 \$50,000 \$50,000 \$50,000 \$50,000 \$50,000 \$50,000 \$50,000 \$50,000 \$50,000 \$50,000 \$50,000 \$50,000 \$50,000 \$50,000 \$50,000 \$50 \$50,000 \$50	Asphalt - Waster Water Treatment Plant entry	\$0	\$6,000	\$0	\$0	\$0	\$0
Education - Sychronized Clock System \$0 \$10,000 \$0 \$0 \$0 \$0 Exterior - Cement Pole Repair \$0 \$14,000 \$0 \$0 \$0 Flag Pole Lighting \$0 \$40,000 \$0 \$0 \$0 HVAC - Remaining 2 Air Handler at PRS - End of Life \$0 \$40,000 \$0 \$0 \$0 Playground - ADA Compliance - Install poured-in-place surfacing \$0 \$0 \$0 \$0 \$0 \$0 replace Classroom Exterior Doors (5) \$0 \$0 \$0 \$0 \$0 \$0 \$0 Replace Classroom Exterior Doors (5) \$0 \$13,448 \$0 \$0 \$0 \$0 Safety - Access Door From Staff Room to Back Garden \$0 \$13,448 \$0 \$0 \$0 Widen Paved Bus Loop \$0 \$15,000 \$0 \$0 \$0 \$0 Install FOB station to Back garden \$0 \$0 \$0 \$0 \$0 \$0 Playground Fence \$0 \$0 \$0 \$0	PRS	\$80,000	\$457,348	\$106,000	\$69,800	\$149,400	\$50,000
Exterior - Cement Pole Repair \$0 \$14,000 \$0 \$0 \$0 Flag Pole Lighting \$0 \$5,000 \$0 \$0 \$0 HVAC - Remaining 2 Air Handler at PRS - End of Life \$0 \$40,000 \$0 \$0 \$0 Lighting- Update Interior Lighting to LED \$0 \$0 \$0 \$0 \$0 Playground - ADA Compliance - Install poured-in-place surfacing \$0 \$0 \$0 \$0 at lower and upper playgrounds \$0 \$0 \$0 \$0 \$0 \$0 Replace Classroom Exterior Doors (5) \$0 \$15,000 \$0 \$0 \$0 Replace Rubber flooring with VCT \$0 \$15,000 \$0 \$0 \$0 Safety - Access Door From Staff Room to Back Garden \$0 \$8,000 \$0 \$0 Widen Paved Bus Loop \$0 \$8,000 \$0 \$0 \$0 FOB Station IT Room \$0 \$48,000 \$0 \$0 \$0 Playground Fence \$0 \$0 <td< td=""><td>Building Repairs and Improvements</td><td>\$0</td><td>\$0</td><td>\$50,000</td><td>\$50,000</td><td>\$50,000</td><td>\$50,000</td></td<>	Building Repairs and Improvements	\$0	\$0	\$50,000	\$50,000	\$50,000	\$50,000
Flag Pole Lighting \$0 \$5,000 \$0 \$0 \$0 HVAC - Remaining 2 Air Handler at PRS - End of Life \$0 \$40,000 \$0 \$0 \$0 Lighting-Update Interior Lighting to LED \$0 \$0 \$0 \$0 \$0 Playground - ADA Compliance - Install poured-in-place surfacing * * * at lower and upper playgrounds \$0 \$0 \$0 \$0 \$0 \$0 Remove out of Service Generator \$0 \$8,900 \$0 \$0 \$0 \$0 Replace Classroom Exterior Doors (5) \$0 \$13,448 \$0 \$0 \$0 Restore restroom Floors (10) \$0 \$15,000 \$0 \$0 \$0 Safety - Access Door From Staff Room to Back Garden \$0 \$0 \$0 \$0 \$0 Install FOB station to back garden \$0 \$0 \$0 \$0 \$0 \$0 Playground Fence \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	Education -Sychronized Clock System	\$0	\$10,000	\$0	\$0	\$0	\$0
HVAC - Remaining 2 Air Handler at PRS - End of Life \$0 \$40,000 \$0 \$0 \$0 Lighting- Update Interior Lighting to LED \$0 \$0 \$0 \$10 \$0 \$0 \$0 \$0 Playground - ADA Compliance - Install poured-in-place surfacing at \$0 \$0 \$0 \$0 \$0 \$0 Remove out of Service Generator \$0 \$8,900 \$0 \$0 \$0 \$0 Replace Classroom Exterior Doors (5) \$0 \$13,448 \$0 \$0 \$0 Restore restroom Floors (10) \$0 \$15,000 \$0 \$0 \$0 Safety - Access Door From Staff Room to Back Garden \$0 \$0 \$0 \$0 \$0 Install FOB station to back garden \$0 \$0 \$0 \$0 \$0 \$0 FOB Station IT Room \$0 \$0 \$0 \$0 \$0 \$0 \$0 Replace Accordian Walls with Permanent Structures \$0 \$0 \$0 \$0 \$0 FOB Station IT Room \$0 \$0 \$0 \$0 \$0 \$0 \$0	Exterior - Cement Pole Repair	\$0	\$14,000	\$0	\$0	\$0	\$0
Lighting- Update Interior Lighting to LED\$0\$0\$0\$15,000\$0\$0Playground - ADA Compliance - Install poured-in-place surfacingat lower and upper playgrounds\$0\$0\$0\$0\$0Remove out of Service Generator\$0\$8,900\$0\$0\$0Replace Classroom Exterior Doors (5)\$0\$0\$15,000\$0\$0\$0Restore restroom Flooring with VCT\$0\$14,448\$0\$0\$0\$0Safety - Access Door From Staff Room to Back Garden\$0\$15,000\$0\$0\$0\$0Install FOB station to back garden\$0\$0\$0\$0\$0\$0FOB Station IT Room\$0\$0\$0\$0\$0\$0Playground Fence\$0\$48,000\$0\$0\$0\$0Designer to exchange Main Office and Library locations\$0\$0\$0\$0\$0\$0Remove out of service emergency generator and abate the\$0\$0\$0\$0\$0\$0Remove out of service emergency generator and abate the\$0\$0\$0\$0\$8,900Rebuild Outdoor Wood Stage\$0\$0\$0\$0\$0\$0\$8,900FOB Station for double doors by Café Door 30\$0\$0\$0\$0\$0\$0\$0Repave Upper Shed Area\$0\$0\$0\$0\$0\$0\$0\$0Repave Upper Shed Area\$0\$10,000\$0\$0\$0\$0	Flag Pole Lighting	\$0	\$5,000	\$0	\$0	\$0	\$0
Playground - ADA Compliance - Install poured-in-place surfacing \$0	HVAC - Remaining 2 Air Handler at PRS - End of Life	\$0	\$40,000	\$0	\$0	\$0	\$0
at lower and upper playgrounds \$0 \$0 \$0 \$0 \$0 Remove out of Service Generator \$0 \$8,900 \$0 \$0 \$0 Replace Classroom Exterior Doors (5) \$0 \$0 \$15,000 \$0 \$0 Replace Rubber flooring with VCT \$0 \$115,000 \$0 \$0 \$0 Restore restroom Floors (10) \$0 \$15,000 \$0 \$0 \$0 Safety - Access Door From Staff Room to Back Garden \$0 \$0 \$8,000 \$0 \$0 Widen Paved Bus Loop \$0 \$80 \$0 \$0 \$0 \$0 Install FOB station to back garden \$0 \$0 \$0 \$0 \$0 \$0 Replace Accordian Walls with Permanent Structures \$0 \$48,000 \$0 \$0 \$0 Playground Fence \$0 \$0 \$0 \$0 \$0 \$0 \$0 Image Service emergency generator and abate the \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0<	Lighting- Update Interior Lighting to LED	\$0	\$0	\$15,000	\$0	\$0	\$0
Remove out of Service Generator\$0\$8,900\$0\$0\$0\$0Replace Classroom Exterior Doors (5)\$0\$0\$13,448\$0\$0\$0Replace Rubber flooring with VCT\$0\$13,448\$0\$0\$0Restore restroom Floors (10)\$0\$15,000\$0\$0\$0Safety - Access Door From Staff Room to Back Garden\$0\$0\$8,000\$0\$0Widen Paved Bus Loop\$0\$0\$8,000\$0\$0\$0Install FOB station to back garden\$0\$0\$0\$0\$0\$0FOB Station IT Room\$0\$0\$0\$0\$0\$0Replace Accordian Walls with Permanent Structures\$0\$48,000\$0\$0\$0Playground Fence\$0\$0\$0\$0\$0\$0Designer to exchange Main Office and Library locations\$0\$0\$0\$0\$0Emergency Generator\$0\$0\$0\$0\$0\$0Remove out of service emergency generator and abate the\$0\$0\$0\$0\$8,900Rebuild Outdoor Wood Stage\$0\$0\$0\$0\$0\$0\$0FOB Station for double doors by Café Door 30\$0\$0\$0\$0\$0\$0Repave Driveway to Dumpster\$0\$10,000\$0\$0\$0\$0\$0Repave Driveway to Dumpster\$0\$10,000\$0\$0\$0\$0\$0Repave Driveway to Du	Playground - ADA Compliance - Install poured-in-place surfacing						
Replace Classroom Exterior Doors (5) \$0 \$0 \$15,000 \$0 \$0 Replace Rubber flooring with VCT \$0 \$13,448 \$0 \$0 \$0 Restore restroom Floors (10) \$0 \$15,000 \$0 \$0 \$0 Safety - Access Door From Staff Room to Back Garden \$0 \$15,000 \$0 \$0 \$0 Widen Paved Bus Loop \$0 \$8,000 \$0 \$0 \$0 \$0 \$0 Install FOB station to back garden \$0 \$0 \$0 \$0 \$0 \$0 \$0 FOB Station IT Room \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 Playeround Fence \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 Designer to exchange Main Office and Library locations \$0	at lower and upper playgrounds	\$0	\$0	\$0	\$0	\$0	\$0
Replace Rubber flooring with VCT\$0\$13,448\$0\$0\$0Restore restroom Floors (10)\$0\$15,000\$0\$0\$0Safety - Access Door From Staff Room to Back Garden\$0\$0\$0\$0\$0Widen Paved Bus Loop\$0\$0\$8,000\$0\$0\$0Install FOB station to back garden\$0\$0\$0\$0\$0\$0FOB Station IT Room\$0\$0\$0\$0\$0\$0Replace Accordian Walls with Permanent Structures\$0\$48,000\$0\$0\$0Playground Fence\$0\$0\$0\$0\$0\$0Designer to exchange Main Office and Library locations\$0\$0\$0\$0\$0Emergency Generator\$0\$0\$0\$0\$0\$0Rebuild Outdoor Wood Stage\$0\$0\$0\$0\$12,000\$0FOB Station for double doors by Café Door 30\$0\$0\$0\$0\$0Repave Driveway to Dumpster\$0\$10,000\$0\$0\$0Repave Upper Shed Area\$0\$10,000\$0\$0\$0	Remove out of Service Generator	\$0	\$8,900	\$0	\$0	\$0	\$0
Restore restroom Floors (10)\$0\$15,000\$0\$0\$0Safety - Access Door From Staff Room to Back Garden\$0\$0\$0\$0\$0Widen Paved Bus Loop\$0\$0\$0\$0\$0\$0Install FOB station to back garden\$0\$0\$0\$0\$0\$0FOB Station IT Room\$0\$0\$0\$0\$0\$0\$0Replace Accordian Walls with Permanent Structures\$0\$48,000\$0\$0\$0\$0Playground Fence\$0\$0\$0\$0\$0\$0\$0Designer to exchange Main Office and Library locations\$0\$0\$0\$0\$0\$0Remove out of service emergency generator and abate the*********************************	Replace Classroom Exterior Doors (5)	\$0	\$0	\$15,000	\$0	\$0	\$0
Safety - Access Door From Staff Room to Back Garden\$0\$0\$0\$8,000\$0\$0\$0Widen Paved Bus Loop\$0\$0\$0\$0\$0\$0\$0\$0Install FOB station to back garden\$0\$0\$0\$0\$0\$0\$0FOB Station IT Room\$0\$0\$0\$0\$0\$0\$0Replace Accordian Walls with Permanent Structures\$0\$0\$0\$0\$0\$0Playground Fence\$0\$0\$0\$0\$0\$0\$0Designer to exchange Main Office and Library locations\$0\$0\$0\$0\$0\$0Emergency Generator\$0\$0\$0\$0\$0\$0\$0Remove out of service emergency generator and abate the\$0\$0\$0\$0\$0\$8,900Rebuild Outdoor Wood Stage\$0\$0\$0\$0\$0\$0\$0FOB Station for double doors by Café Door 30\$0\$0\$0\$0\$0\$0Repave Driveway to Dumpster\$0\$10,000\$0\$0\$0\$0Repave Upper Shed Area\$0\$35,000\$0\$0\$0\$0	Replace Rubber flooring with VCT	\$0	\$13,448	\$0	\$0	\$0	\$0
Widen Paved Bus Loop\$0\$8,000\$0\$0\$0Install FOB station to back garden\$0\$0\$0\$0\$0\$0FOB Station IT Room\$0\$0\$0\$0\$0\$0\$0Replace Accordian Walls with Permanent Structures\$0\$48,000\$0\$0\$0\$0Playground Fence\$0\$0\$0\$0\$0\$0\$0Designer to exchange Main Office and Library locations\$0\$0\$0\$0\$0\$0Emergency Generator\$0\$0\$0\$0\$58,500\$58,500Remove out of service emergency generator and abate the remaining asbestos\$0\$0\$0\$0\$58,900Rebuild Outdoor Wood Stage\$0\$0\$0\$0\$0\$12,000FOB Station for double doors by Café Door 30\$0\$0\$0\$0\$0\$0Repave Driveway to Dumpster\$0\$10,000\$0\$0\$0\$0Repave Upper Shed Area\$0\$35,000\$0\$0\$0\$0	Restore restroom Floors (10)	\$0	\$15,000	\$0	\$0	\$0	\$0
Install FOB station to back garden\$0\$0\$0\$0\$0FOB Station IT Room\$0\$0\$0\$0\$20,000Replace Accordian Walls with Permanent Structures\$0\$48,000\$0\$0\$0Playground Fence\$0\$0\$0\$0\$0Designer to exchange Main Office and Library locations\$0\$0\$0\$0\$0Emergency Generator\$0\$0\$0\$0\$0Remove out of service emergency generator and abate the\$0\$0\$0\$0remaining asbestos\$0\$0\$0\$0\$8,900Rebuild Outdoor Wood Stage\$0\$0\$0\$0\$12,000FOB Station for double doors by Café Door 30\$0\$0\$0\$0\$0Repave Driveway to Dumpster\$0\$10,000\$0\$0\$0\$0Repave Upper Shed Area\$0\$35,000\$0\$0\$0\$0	Safety - Access Door From Staff Room to Back Garden	\$0	\$0	\$8,000	\$0	\$0	\$0
FOB Station IT Room\$0\$0\$0\$0\$0\$20,000Replace Accordian Walls with Permanent Structures\$0\$48,000\$0\$0\$0\$0Playground Fence\$0\$0\$0\$12,000\$0\$0\$0Designer to exchange Main Office and Library locations\$0\$0\$0\$0\$0\$0Emergency Generator\$0\$0\$0\$0\$0\$0\$0Remove out of service emergency generator and abate the\$0\$0\$0\$0\$0\$0Rebuild Outdoor Wood Stage\$0\$0\$0\$0\$0\$0\$0FOB Station for double doors by Café Door 30\$0\$0\$0\$0\$0\$0Repave Driveway to Dumpster\$0\$10,000\$0\$0\$0\$0Repave Upper Shed Area\$0\$35,000\$0\$0\$0\$0	Widen Paved Bus Loop	\$0	\$8,000	\$0	\$0	\$0	\$0
Replace Accordian Walls with Permanent Structures\$0\$48,000\$0\$0\$0Playground Fence\$0\$0\$0\$0\$0Designer to exchange Main Office and Library locations\$0\$0\$0\$0\$0Emergency Generator\$0\$0\$0\$0\$0Remove out of service emergency generator and abate the V V V V remaining asbestos\$0\$0\$0\$0\$8,900Rebuild Outdoor Wood Stage\$0\$0\$0\$0\$12,000FOB Station for double doors by Café Door 30\$0\$0\$0\$0\$0Repave Driveway to Dumpster\$0\$10,000\$0\$0\$0Repave Upper Shed Area\$0\$35,000\$0\$0\$0	Install FOB station to back garden	\$0	\$0	\$6,000	\$0	\$0	\$0
Playground Fence\$0\$0\$12,000\$0\$0Designer to exchange Main Office and Library locations\$0\$0\$0\$0\$0Emergency Generator\$0\$0\$0\$0\$0Remove out of service emergency generator and abate the\$0\$0\$0remaining asbestos\$0\$0\$0\$0\$8,900Rebuild Outdoor Wood Stage\$0\$0\$0\$0\$12,000FOB Station for double doors by Café Door 30\$0\$0\$0\$0\$0Repave Driveway to Dumpster\$0\$10,000\$0\$0\$0Repave Upper Shed Area\$0\$35,000\$0\$0\$0	FOB Station IT Room	\$0	\$0	\$0	\$0	\$20,000	\$0
Designer to exchange Main Office and Library locations\$0\$0\$0\$0\$10,000\$0Emergency Generator\$0\$0\$0\$0\$0\$0\$58,500Remove out of service emergency generator and abate the\$0\$0\$0remaining asbestos\$0\$0\$0\$0\$0\$8,900Rebuild Outdoor Wood Stage\$0\$0\$0\$0\$12,000FOB Station for double doors by Café Door 30\$0\$0\$0\$0\$0Repave Driveway to Dumpster\$0\$10,000\$0\$0\$0Repave Upper Shed Area\$0\$35,000\$0\$0\$0	Replace Accordian Walls with Permanent Structures	\$0	\$48,000	\$0	\$0	\$0	\$0
Emergency Generator\$0\$0\$0\$0\$0\$58,500Remove out of service emergency generator and abate theremaining asbestos\$0\$0\$0\$0\$8,900Rebuild Outdoor Wood Stage\$0\$0\$0\$0\$12,000FOB Station for double doors by Café Door 30\$0\$0\$0\$0\$0\$0Repave Driveway to Dumpster\$0\$10,000\$0\$0\$0\$0Repave Upper Shed Area\$0\$35,000\$0\$0\$0\$0	Playground Fence	\$0	\$0	\$12,000	\$0	\$0	\$0
Remove out of service emergency generator and abate the remaining asbestos\$0\$0\$0\$0\$8,900Rebuild Outdoor Wood Stage\$0\$0\$0\$0\$12,000FOB Station for double doors by Café Door 30\$0\$0\$0\$0\$0Repave Driveway to Dumpster\$0\$10,000\$0\$0\$0Repave Upper Shed Area\$0\$35,000\$0\$0\$0	Designer to exchange Main Office and Library locations	\$0	\$0	\$0	\$10,000	\$0	\$0
remaining asbestos\$0\$0\$0\$0\$8,900Rebuild Outdoor Wood Stage\$0\$0\$0\$0\$12,000FOB Station for double doors by Café Door 30\$0\$0\$0\$0\$0Repave Driveway to Dumpster\$0\$10,000\$0\$0\$0Repave Upper Shed Area\$0\$35,000\$0\$0\$0	Emergency Generator	\$0	\$0	\$0	\$0	\$58,500	\$0
Rebuild Outdoor Wood Stage\$0\$0\$0\$12,000FOB Station for double doors by Café Door 30\$0\$0\$0\$0\$0Repave Driveway to Dumpster\$0\$10,000\$0\$0\$0Repave Upper Shed Area\$0\$35,000\$0\$0\$0	Remove out of service emergency generator and abate the						
FOB Station for double doors by Café Door 30 \$0 \$0 \$0 \$0 \$0 \$0 Repave Driveway to Dumpster \$0 \$10,000 \$0 \$0 \$0 \$0 Repave Upper Shed Area \$0 \$35,000 \$0 \$0 \$0	remaining asbestos	\$0	\$0	\$0	\$0	\$8,900	\$0
Repave Driveway to Dumpster \$0 \$10,000 \$0 \$0 \$0 Repave Upper Shed Area \$0 \$35,000 \$0 \$0 \$0	Rebuild Outdoor Wood Stage	\$0	\$0	\$0	\$0	\$12,000	\$0
Repave Upper Shed Area \$0 \$35,000 \$0 \$0 \$0	FOB Station for double doors by Café Door 30	\$0	\$0	\$0	\$9,800	\$0	\$0
	Repave Driveway to Dumpster	\$0	\$10,000	\$0	\$0	\$0	\$0
Redesign Office and Library - Security Vestbule w Windows, etc. \$80,000 \$250,000 \$0 \$0 \$0 \$0 \$0	Repave Upper Shed Area	\$0	\$35,000	\$0	\$0	\$0	\$0
	Redesign Office and Library - Security Vestbule w Windows, etc	\$80,000	\$250,000	\$0	\$0	\$0	\$0

		2021-2022 Capi	tal Projects			
Row Labels	Sum of FY 2021	Sum of FY 2022	Sum of FY 2023	Sum of FY 2024	Sum of FY 2025	Sum of FY 2026
South	\$20,000	\$148,000	\$1,734,000	\$120,000	\$1,624,000	\$50,000
AC Unit for Third Floor - replace failing window units	\$0	\$0	\$11,000	\$0	\$0	\$0
Add Glycol to Heating System	\$0	\$10,000	\$0	\$0	\$0	\$0
Add loads to existing generator	\$0	\$0	\$35,000	\$0	\$0	\$0
Automatic floor machine	\$0	\$0	\$0	\$0	\$0	\$0
Blinds for Cafeteria	\$0	\$8,000	\$0	\$0	\$0	\$0
Building Repairs and Improvements	\$0	\$50,000	\$50,000	\$50,000	\$50,000	\$50,000
Exterior - Paint outside trim doors and railings	\$0	\$0	\$30,000	\$0	\$0	\$0
Floors - Replace VCT in Hall	\$0	\$0	\$0	\$0	\$8,000	\$0
Lighting - Upgrade Interior Lighting to LED	\$0	\$0	\$20,000	\$0	\$0	\$0
New vertical blinds for cafeteria	\$0	\$0	\$0	\$0	\$0	\$0
Roofs - Major Repair Replacement	\$0	\$0	\$1,500,000	\$0	\$0	\$0
Safety - Build security entrance in front hallway - Lock off Educat	i \$0	\$0	\$20,000	\$0	\$0	\$0
Sand, stain and repoly all of the cabinets and door trim (oak) in b	ι \$0	\$10,000	\$0	\$0	\$0	\$0
Temperature Control in the TV Studio	\$0	\$0	\$0	\$0	\$0	\$0
Ventilation - Ceiling Fans for the Gym	\$0	\$0	\$8,000	\$0	\$0	\$0
Heat and Efficiency - Rebuild Water Distribition Pumps and Install						
VFD. Combination of Capital and Green Grant (15K)	\$0	\$0	\$0	\$0	\$0	\$0
HVAC Duct Maintenance & Test	\$20,000	\$0	\$0	\$0	\$0	\$0
Playground Matting	\$0	\$0	\$10,000	\$0	\$0	\$0
Building Envelope Repairs	\$0	\$0	\$0	\$0	\$50,000	\$0
Storage Shed	\$0	\$0	\$0	\$0	\$6,000	\$0
Asphalt Roof Replacement/Library/Cafeteria	\$0	\$0	\$0	\$0	\$1,500,000	\$0
Security - Build Wall with doors between LMC and office in main	ł \$0	\$0	\$0	\$20,000	\$0	\$0
BMS Upgrades and Replcements 3 year project	\$0	\$40,000	\$40,000	\$40,000	\$0	\$0
Door Hardware - Interior	\$0	\$0	\$10,000	\$10,000	\$10,000	\$0
Door Hardware Exterior	\$0	\$30,000	\$0	\$0	\$0	\$0

2021-2022 Capital Projects

	0	2021-2022 Capi	•	0	0	0
bw Labels					Sum of FY 2025	Sum of FY 2026
System	\$830,568	\$1,233,689		•	. , ,	
Copiers	\$25,000	\$25,000				
Digital Radio System	\$0	\$90,000				•
Energy Efficiency Projects - System Wide	\$20,000	\$0	\$0	\$0	\$C	*
Fire Alarm Monitoring Changes 6 Buildings - All Buildings- See		\$0	\$0	\$0	\$C	
Instructional Equipment	\$47,588	\$47,588	\$47,588	\$47,588	\$47,588	\$47,588
Maintenance Equipment (FY 19, estimate for outer years)	\$20,900	\$20,900	\$20,900	\$20,900	\$20,900	\$20,900
New Pad for loading Dock Bldg 179	\$0	\$0	\$0	\$8,000	\$C	\$
New Website Development	\$0	\$0	\$0	\$0	\$C	\$
Roofs - Repairs all Buildings	\$50,000	\$50,000	\$50,000	\$50,000	\$50,000	\$50,000
Security - Additional Surveillance Cameras (security)/ Radio						
Replacements	\$20,000	\$20,000	\$20,000	\$20,000	\$20,000	\$20,000
Technology - Capital Requests - Baseline	\$240,780	\$250,780	\$260,780	\$270,780	\$452,203	\$462,20
Technology - Enhancements and New Initiatives	\$100,000	\$100,000	\$100,000	\$100,000	\$100,000	\$100,00
Technology - Major Infrastructure Replacements and Chromeboo	ok					
Replacement	\$199,300	\$166,500	\$192,600	\$132,900	\$266,250	\$266,25
Transportation - Replace School Transportation Vans	\$0	\$43,820				
Unanticipated Major Repairs	\$35,000	\$35,000				
Vehicles - Dump Truck Replacement	\$0	\$80,000		\$0		
Z- Bldg. 179 Sprinklers	\$0	\$0	\$212,587		\$C	
Z- Building 179 Renovations (Excludes Sprinklers)	\$0	\$0	\$354,312		\$C	
Abate Asbestos in building 179	\$0	\$0	\$0 \$0		\$C	•
Abate Asbestos in building 12	\$0	\$0	\$0 \$0	\$0	\$15,000	
Gynmnastics Equipment New Initiative (Education Fund)	\$0	\$0	\$0 \$0	\$0	¢.0,000 \$0	
Repair/Paint exterior Transportation Building	\$0 \$0	\$0 \$0	\$0 \$0	\$0	\$18,000	
Portable Partitions for Special Events (40)	\$0 \$0	\$29,600	\$0 \$0	\$0 \$0	¢10,000 \$0	
Major 20 year grounds maintenance to cut back vegetation and		\$75,000			\$C \$C	
Carpeting/Flooring - Area Carpet/Flooring Replacement Plan -		\$14,500			•	
Vehicles Maintenance - Replacement Plan (see dump truck al		\$1 \$1	\$13,000		\$59,740	
	\$0,000 \$0	\$80,000	\$09,740 \$0	\$39,740	\$39,740 \$0	. ,
Facilites and Space Study - 10 Year Master Plan	\$0 \$0	\$105,000		\$0 \$0	\$C	
Purchase Big Yellow Buses coming off Lease Town Wide		· ·			•	
	\$0	\$41,800			•	-
Building Repairs and Improvements	\$0 \$0	\$15,000				
Depot - Replace Depot Garage Doors	\$0	\$0	\$17,940		\$C	•
Additional hookups to emergemcy generator at DEPOT	\$0 \$0	\$6,800	\$0	\$0	\$C	
Sprinkler Head Replacement	\$0	\$20,000		\$0	\$0	
rand Total	\$1,323,218	\$6,410,563	\$6,588,942	\$1,487,556	\$3,820,924	\$1,502,50
escheduled Reconciliation	\$22,000					
nscheduled	\$4,648					
ticles (Windows, Etc) perating Capital	\$1,349,866	-\$4,190,190 \$2,220,373				